



SUZUKI CANADA INC.

HEAD OFFICE/SIÈGE SOCIAL

100 East Beaver Creek Rd., Richmond Hill, ON L4B 1J6

Telephone: (905) 889-2600 Facsimile: (905) 764-1574

Website: www.suzuki.ca

SAFETY RECALL CAMPAIGN

August, 2007

Dear Suzuki Owner:

Suzuki has determined that a defect which relates to safety exists in certain 2007 DF300 outboard motors. An incorrectly positioned shift actuator sealing ring may allow the entry of water which can cause corrosion within the shift actuator. Eventually, the corrosion can cause restricted movement of the internal gears within the shift actuator which may prevent the shift actuator from responding to the operator's movement of the shift lever. If this occurs, a "check shift control" message will appear in the malfunction display, a beep will be heard and the motor will remain in the last selected gear.

To prevent this occurrence, Suzuki Canada Inc. is conducting a Safety Recall Campaign to replace the shift actuator on affected outboard motors. According to our records, you own one of the outboard motors affected by this Campaign.

Please contact your Suzuki dealer to schedule an appointment for this Safety Recall Campaign. Campaign instructions have already been sent to your dealer and the campaign can be completed in approximately one hour if you have an appointment. Additional time may be required to schedule and process your outboard motor. If your dealer has a large number of boats or motors awaiting service, this additional time may be significant.

We sincerely regret any inconvenience this Safety Recall Campaign may cause, but we are certain you understand our interest in your continued satisfaction with your new Suzuki outboard motor.

Sincerely,

SUZUKI CANADA INC.

WESTERN OFFICE/BUREAU DE L'OUEST
110-6351 Westminster Hwy., Richmond, BC V7C 4V4
Telephone: (604) 273-0388 Fax: (604) 278-0520

6

EASTERN OFFICE/BUREAU DE L'EST
4111 boul. Poirier, St-Laurent, QC H4R 2G9
Téléphone: (514) 956-7986 Fax: (514) 956-1004